

# True RMS AC Flex Clamp Meter

**TENMA™**

**RoHS  
Compliant**



## Features

- Ergonomically Designed One Hand Operation
- 3000 Count Large Scale LCD Display with Backlit
- 3000A AC Current
- Head Cable Length 18" (457mm)
- Auto Ranging
- Data Hold & Max/Min
- 7.5mm Coil Diameter for Tight Space Measurement
- Low Battery Indication
- CAT IV 600V/CAT III 1000V Safety Standard

## Specifications

Function	Range	Resolution	Accuracy (% of reading + digits)
AC Current 50~400Hz True RMS	30.00A AC	0.01A	$\pm(3.0\% + 8d)$
	300.0A AC	0.1A	$\pm(3.0\% + 5d)$
	3000A AC	1A	$\pm(3.0\% + 5d)$

**Note:** Accuracy is given as  $\pm$ (% of reading + counts of least significant digit) at 23°C  $\pm$ 5°C, with relative humidity less than 80%RH. The measured conductor is placed in the center of the coil.

## Part Number Table

Description	Part Number
True RMS AC Flex Clamp Meter, 3000A, 457mm Cable	72-14435

**TENMA™**